## Initial quick test log

Model series/Model

168.033

Workshop ID

designation

VIN

---1680332J64××××

Steering

RIGHT

Total distance driven

Version

5.1.6/10/2005

(2005-09-15)

**Battery voltage** 

12.11 V

M - Engine control monolith				- f -	
MB numbe	r	HW version	SW version 44.2000	Diagnosis version	Pin
1661500179	9	00.2000		3/06	7
Code Text				Status	
P0136-002			sensor downstream Todeceleration phase.	WC) is not	Not defined
P0170-002	Self-adaptation: Mixture is too lean.				Not defined
P0170-002	Self-adaptation: Mixture is too lean.				STORED
P1813	S40/3 (Clutch pedal switch) : Possible cause: Open circuit or Short circuit to ground				Not defined
P0100-002	B2/5 (Hot film MAF sensor): The signal voltage is too high.			o high.	Not defined
P0100-001	There is a sporadic fault in component B2/5 (Hot film MAF sensor).				Not defined
P0100-001	There is a sporadic fault in component B2/5 (Hot film MAF sensor).				STORED
P0100-004	B2/5 (Hot film MAF sensor): The signal voltage is too low.			o low.	Not defined
P0100-004	B2/5 (Hot film MAF sensor) : The signal voltage is too low.				STORED

SP - Electronic stability program				- f -	
MB numbe	3 1	HW version 10.2001	SW version 10.2001	Diagnosis version 2/00	Pin 9
Code		Text			Status
C1140-024 N49 (steering angle sensor)			STORED		
C1143	C1143 Component B34/2 (ESP pressure sensor 2) is faulty.				STORED
C1504-009	The system is switched off. Steering angle sensor is not initialized.				STORED

B - Airbag					- f -
MB numb 00182031		HW version 51.1998	SW version 51.1998	Diagnosis version 5/00	Pin 13
Code		Text			Status
27-000	27-000 Fault in communication with component B48 (Front passenger seat occupied and child seat recognition) or there is a cable fault.			STORED	
37-064	Seat is installed, but component X55/4 (Right front seat contacting strip) is not plugged in.			STORED	

RFL - Radio frequency locking/electric central locking				-!-
MB number	HW version	SW version	Diagnosis version	Pin
			0.0	1

CM - Instrument cluster with maintenance interval display				- f
MB number	HW version	SW version	Diagnosis version	Pin
1685409011	34.2001	46.2000	3/20	15